


5. Exploded View



Model	Classification	Description	Part Number	Location Number	Remark
L3UC362FAB	Cooling Only	Compressor	TBZ31755601	554160A	Service Valve
		Harness,Multi	EAD35871801	W6631A	
		Compressor	2520UHFK2DB	554160B	Barrier Side
		Harness,Multi	EAD35871802	W6631B	

Note) * Please ensure GCSC since the replacement parts may be changed depending upon the buyer's request.
Please check the correct parts in View RPL(Replacement Part List) on GCSC.
(GCSC Website <http://biz.lgservice.com>.)

